

## A/C Precept Room Condensation

### Location:

Air Conditioner condenser in Precept Room

### Problem:

Moisture accumulating on A/C condenser is not being caught by drain pan inside plenum and drips to floor.

See Kit regarding how to get at the drain pan and resolve problem.  
May require some sheet metal cutting.