

## Eyebrow

### Location:

South wall of gym-eyebrow

### Problem:

Shingles deteriorating

### Action:

Replace shake shingles with metal roofing

See Kit about getting special cutter for metal and instructions on roofing.